

TEST CERTIFICATE

Site Number Transaction Number **840-Emirates Auctions**

39053417 (CC10006)

Transaction Date

15 Nov 2022, 16:28:19

Oueue Number 622820

Chassis Number

WDC0G4JB8KV165104

Engine Number

Vehicle Class

Manufacturer

Model

Model Year

Color

Mileage

Fuel Type

No. Of Cylinders

Specification

Car

Mercedes

GLC 300

2019

White

73981 Km

Petrol

Imported

حالة الجير النظرى

مدكار

اخري

الارضية

DEFECT	REMARKS
DEFECT	KLIVIAKKS

Of Italiania stori Condition		انجير
01.A Road Test	NOT CHECK	فحص علي الطريق

SIGN OF LEAK

01.B Visual Gear Box Condition

02.B Fenders

02 Body

جسم المركبة

02.A Paint BODY PORTION REPAIRED, REPAINTED & MINOR DENT الصبغ

,SCRATCHES,

PORTION REPAIRED, REPAINTED

FRONT BOTH SIDE REPAINTED REFITTED & REAR LEFT SIDE

02.C Sign of front accident وجود مؤشر لحادث في المقدمة

02.D Other FRONT FENDER FRAME, BUMPER FRAME, RADITOR

SUPPORT, BULKHEAD REPAIRED

02.E Bonnet **REPAINTED & REFITTED** غطاء المحرك

02.F Floor UNDER FLOOR COVERED, CHECKED VISIBLE AREA

03 Tires and Rims Condition الاطارات

BOTH SIDE 2017 EXPIRED 03.A Front Tyre الاطار الامامي

BOTH SIDE 2019 03.B Rear Tyre الاطار الخلفى

04 Interior Condition الحاله الداخلية

DEFECT	REMARKS	
04.A Roof Ceiling	PORTION LOOSE	بطانه السقف
04.B AC Condition	ОК	المكيف
05 Chassis Condition		الشاصي
05.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
07 Suspension System		ممتص الصدمات
07.A Arms	REAR RIGHT SIDE CONTROL ARM BEND	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.