CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2911983
Transaction Date	26 Oct 2026, 12:51:07
Site Name	840 - Emirates Auctions
Transaction Number	45400279 (CC10009) (CC10025)



Vehicle Details

Chassis Number	JTHBK1GG6F*******
Specification	GCC Specification
Make	Lexus
Model	ES 350
Model Year	2015
Color	White
Mileage	250048 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED , PORTION GETTING RUSTY	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED , SHOCK NOT WORKING	غطاء المحرك
01.G Pillars	RIGHT SIDE C/ PILLAR OUTER PANEL REPAIRED	القوائم
01.H Sign of front accident	FRONT BUMPER FRAME FENDER FRAME BULKHEAD ,RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVER,CHECKED VISIBLE AREA ONLY FRONT LEFT SIDE OUTER SKIRT ALIGN REPAIRED,CHASSIS PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Mount	TOP MOUNT RUBBER CUT	كرسي
03.B Engine Visual Condition	REFITTED MINOR OIL LEAK GETTING RUSTY, SUMB DENT	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED, GETTING RUSTY MINOR JERKING	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 WORN OUT CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Axle	BOOT CUT	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT / INTERIOR PARTS GETTING RUSTY	اخري
10.B AC Condition	OK	المكيف
10.C Dash Board	MINOR SCRATCH MELTED	لوحة القياده
10.D Door Panel	WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT PORTION CRACK	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae