





Test Certificate

Site Number	: 752-AL AWEER	Plate Code	: 0
Transaction Number	: 27588644	Plate Category	: PRIVATE
Transaction Date	: 05 JUL 2021 14:27:35	Plate Number	: 70223 EA
Queue Number	: 364747	Import Doc. Ref.	:
Chassis Number	: 5TDZZ3DC1HS870223	Manufacturer/Model	: TOYOTA/SIENNA
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots		المحور
		RIGHT SIDE INNER & OUTER AXLE BOOT GREASE LEAK
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		TIRE DOT 2019 / 2018
05 Body		الهيكل
05.02 - Paint		الصنع
		BODY MINOR SCRATCH & DENT
05.04 - Fenders		المدكار
		FRT FENDER F/FRAME & APRON REPAIRED
05.05 - Bumpers		الدعامية
		FRT BUMPER & B/FRAME REPLACED
05.07 - Floor		الارضية
		RUNNING BOARD COVER REPAIRED
05.08 - Chassis (Frame)		الشاصية
		FRONT RIGHT SIDE CHASSIS DENT
06 General Items		الاشياء العامة
06.21 - Battery Condition		حالة البطارية
		BATTERY MOUNTING BRACKET MISSING
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		104582 MILES
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
		VEHICLE PULLING TO RIGHT WHILE DRIVING
09.09 - Engine And Gear Box Performance Ok		فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		اثر حادث في مقدمة المركبة
		BULKHEAD & RADIATOR SUPPORT



Test Certificate

Site Number	: 752-AL AWEER	Plate Code	: 0
Transaction Number	: 27588644	Plate Category	: PRIVATE
Transaction Date	: 05 JUL 2021 14:27:35	Plate Number	: 70223 EA
Queue Number	: 364747	Import Doc. Ref.	:
Chassis Number	: 5TDZZ3DC1HS870223	Manufacturer/Model	: TOYOTA/SIENNA
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.16 - Sign Of Side Accident	FRAME REPAIRED	أثر حادث في جوانب المركبة
09.23 - Air Bag Damaged	BOTH SIDE QUARTER PANEL REPAIRED	المخدة الهوائية لا تعمل
09.25 - Body Repainted	AIRBAG DEPLOYED & CUT	أثر صنيغ في المركبة
	BODY PORTIONS REPAINTED	
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p>شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية</p>		

Test Certificate



✓ PASS

Vehicle
Registration



Custom Certificate :	12355412
Chassis No :	5TDZZ3DC1HS870223
Vehicle Make :	TOYOTA
Vehicle Model :	SIENNA
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	168311 Kms.
Origin : United States	Model Year : 2017
Gear Type : --	Engine Size : 3000 CC
Engine No : NIL	Horse Power : 264
Axles No : 2	Cylinders : 6
No Of Doors : 4	No Of Seats : 7
G. V. W. : 2715 Kgs.	Empty Weight : 1600 Kgs.

Certificate Number :	5-TAS-2021-14671191
Inspection Date :	26-07-2021
Certificate Print Date :	26-07-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	4 min 12 sec
Appointment Ref Number :	--
Start Time : 12:55	End Time : 12:59
Lane : 03	Token No. : 138
Attempt : 2	Prints No : 1

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

24044 KM	2475 L	4010 AED	6.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks:

FRONT RIGHT CHASSIS MINOR DENT/BULK HEAD , RADIATOR SUPPORT ,FRONT RIGHT FENDER AND FENDER FRAME REPAIRED /RIGHT SIDE QUARTER PANEL REPAIRED .

Payment Details

Inspection Performed by 62424	Payment Method VTP Credit Account	Transaction Number 14671191	Service Fees AED 70 Collected on 26/07/2021
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for.

