CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2913294
Transaction Date	31 Oct 2026, 12:06:36
Site Name	840 - Emirates Auctions
Transaction Number	69198489 (CC10009) (CC10011)



Vehicle Details

Chassis Number	WP1ZZZ9PZ8*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2008
Color	Unknown
Mileage	189082 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPLETELY COVERED MUDDY OILY CHECKED VISIBLE AREA	الارضية
01.E Bumper	MISALIGN,PORTION CRACK	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Pillars	LEFT SIDE A/PILLAR COVER PART MISSING	القوائم
01.H Trunk	NOT OPEN	صندوق
01.I Vehicle Color	ORANGE	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY MUDDY OILY COVERED, CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER FLOOR CHASSIS FENDER & OPEN REAR TRUNK FOR RECHECK VIN AND CHASSIS PROPERLY	اخري
02.C Chassis Number	MANUFACTUR & WIND SHIELD STICKER DAMAGED SUSPECT REFITTED , OTHER NOT CHECKED	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Exhaust System		نظام العادم

Condition	Remarks	الحالة
04.A Catalytic Converter	CUT REWELDED	دبة البيئة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK REFITTED, NOT CHECKED	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	2023/2021 CRACKED EXPIRED	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Hand Brake	SWITCH MISSING	فرامل اليد
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR MODIFIED PARTS REFITTED GETTING RUSTY SIGN OF FLOODED	اخري
08.B AC Condition	NOT CHECK	المكيف
08.C Dash Board	PORTION DAMAGED ,LETAHER LOOSE WORN OUT, LEFT SIDE INNER ELECTRIC PARTS MISSING	لوحة القياده
08.D Steering Wheel and control buttons	WORN OUT INNER STEERING WHEEL PARTS & OBD CONNECTER MISSING	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	SIDE COVER PARTS MISSING	ذراع نقل السرعات
08.F Engine Start Button	IGNIATION SWITH DAMAGED SIDE PARTS MISSING	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae