



### Test Certificate

|                     |                          |                    |                    |
|---------------------|--------------------------|--------------------|--------------------|
| Site Number         | : 840-TASJEEL EM AUCTION | Plate Code         | : 0                |
| Transaction Number  | : 18601246               | Plate Category     | : PRIVATE          |
| Transaction Date    | : 24 NOV 2019 14:24:38   | Plate Number       | : 80716 EA         |
| Queue Number        | : 120553                 | Import Doc. Ref.   | :                  |
| Chassis Number      | : SALGA2EFXEA180716      | Manufacturer/Model | : RANGEROVER/VOGUE |
| Engine Number       | :                        | Model Year         | : 2014             |
| Vehicle Class       | : LIGHT VEHICLE          | Vehicle Color      | : WHITE            |
| Service / Indicator | : DSC AUCTION            |                    |                    |

#### Statement of Vehicle Condition

| Defect                                     | Result | Remarks  |
|--|--------|--|
| AUTOMATIC TEST:                            |        |  |
| 13 Brake System                            |        | الفرامل  |
| 13.04 - Brake Test                         | Passed | فحص الفرامل  |
| 14 Exhaust Gas Test                        |        | الغاز العادم والكربون  |
| 14.01 - Exhaust Gas Test                   | Passed | فحص الغاز العادم-الكربون   |
| VISUAL TEST:                               |        |  |
| 04 Tires Rims                              |        | الاطارات والعجلات  |
| 04.01 - Front Left And Right Hands Tires   |        | الاطارات الامامية<br>FRONT TYRE DOT 2018 & 2019, REAR<br>TYRE DOT 2019 |
| 05 Body                                    |        | الهيكل   |
| 05.02 - Paint                              |        | الصنع<br>BODY SCRACHES   |
| 09 Auction                                 |        | الفحص الكامل   |
| 09.06 - Chassis Ok                         |        | الشاصي جيد   |
| 09.09 - Engine And Gear Box Performance Ok |        | فحص حالة الماكينة والجير   |
| 09.25 - Body Repainted                     |        | اثر صنع في المركبة<br>BODY PORTION REPAINTED                           |

The Test Certificate Shows the test Result at the time of inspection only.