

Queue Number 2848447

Transaction Date 08 Oct 2026, 12:03:38

Site Name
840 - Emirates AuctionsTransaction Number
25414960 (CC10006) (CC10006)

Vehicle Details

Chassis Number	WBAKB8100A*****
Specification	GCC Specification
Make	BMW
Model	730 LI
Model Year	2010
Color	Silver
Mileage	224967 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	MINOR DENTS, SCRATCHES, PORTION RUSTY, SLIGHTLY FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERD, MUDDY, COVER PORTION DAMAGED,	الارضية
01.D Bumper	MISALIGN PORTION CRACKED	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	COVERD, CHECKED VISIBLE AREA ONLY OK	الشاسيه
--------------	--------------------------------------	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED	كرسي
03.B Other	ENGINE NOT START GEAR HAVE ISSUE	اخرى
03.C Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	GEAR HAVE ISSUE STACK IN (N), NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
-----------------	----------------	----------------

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	BODY LEVEL LOW	ممتص الصدمات
07.B Arms	BUSHES CUT	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Steering Box	LEAK	جهاز المقود
08.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
08.C Axle	BOOT CUT	اكسلات
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS RUSTY	اخرى
09.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae