CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2977943
Transaction Date	12 Nov 2026, 13:07:03
Site Name	840 - Emirates Auctions
Transaction Number	64240535 (CC10008) (CC10011)



Vehicle Details

Chassis Number	WA1CFCFP0H*******
Specification	GCC Specification
Make	Audi
Model	Q5
Model Year	2017
Color	Grey
Mileage	77555 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAIRED REPAINTED,RIGHT SIDE BOTH REPAINTED PORTION REPAIRED & FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE,REAR BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN PORTION CRACK	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.G Trunk	LUGGAGE SHADE MISSING	صندوق
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK ,COMPONENTS REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 WORN OUT CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED,BRACKET DAMAGED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING MINOR RUSTY	اخري
08.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
08.C AC Condition	OK	المكيف
08.D Power Window Switch And Glass	REAR RIGHT SIDE CURTAIN CASE DAMAGED	مفتاح النافذه و الزجاج
08.E Audio	SWITCH PORTION DAMAGED	صوتيات
08.F Roof Ceiling	PORTION LOOSE	بطانه السقف
08.G Sun Visor	RIGHT SIDE MISSING	حاجب الشمس
08.H Door Panel	PORTION GETTING WORN OUT	لوحة بطانة الباب
08.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.J Gear Shifting Lever	KNOB WORN OUT,DUST COVER CRACKED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae