



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	17 Oct 2021, 17:57:20
Transaction Number	36752103 (CC10006)	Queue Number	312309



Chassis Number	VF3WC5FWF9W001948
Engine Number	
Vehicle Class	Car
Manufacturer	Peugeot
Model	207
Model Year	2009
Color	Black
Mileage	193508 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,BODY PAINT PORTION FADED ,MINOR DENT,SCRATCHES	الصبغ
01.B Fenders	REAR LEFT FENDER REPAINTED PORTION,REPAIRED&FRONT RIGHT REPAINTED	مدكار
01.C Trunk	REPAINTED&PORTION REPAIRED	صندوق
01.D Door Handle &Lock	REAR RIGHT DOOR NOT OPENING	مقابض الأبواب والأقفال
01.E Floor	REAR COMPARTMENT, PANEL, BACK PANEL REPAIRED	الارضية
01.F Bumper	REPAINTED	دعامية
02 Interior Condition		الحاله الداخليه
02.A Door Panel	INNER DOOR PAD DAMAGED	لوحة بطانة الباب
02.B Power Window Switch	REAR RIGHT POWER WINDOW SWITCH MISSING	مفتاح النافذه
02.C Mirror	BOTH BROKEN AND FIXED BY TABE	المرايا
02.D AC Condition	OK	المكيف
02.E Dash Board	CONSOLE BOX HANDLE BROKEN	لوحة القيادة
03 Lights		الاضاءة
03.A Head Light	FADED	الاضاءة الرئيسية

DEFECT	REMARKS	
04 Wipers and Arms		المساحات
04.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
05.C Spare Tire &Tools	SPARE TIRE ONLY RIM	الاطار الاحتياطي و العدة
06 Engine Condition		المحرك
06.A Engine Condition	MINOR OIL LEAK	حالة المحرك
06.B Smoke	WHITE SMOKE	دخان
07 Transmission Condition		الجير
07.A Gear Box	MINOR OIL LEAK	الجير
07.B Road Test	NOT CHECK	فحص علي الطريق
08 Suspension System		ممتص الصدمات
08.A Arms	FRONT LOWER BUSHES CRACKED	ازرع
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
09.B Axel	LEFT AXLE BOOT CUT	اكسلات
10 Chassis Condition		الشاصي
10.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.