

Queue Number 2884397

Transaction Date 19 Oct 2026, 17:41:55

Site Name
840 - Emirates AuctionsTransaction Number
44612654 (CC10013) (CC10011)

Vehicle Details

Chassis Number	W1WV0LEZ7M*****
Specification	GCC Specification
Make	Mercedes
Model	V 250
Model Year	2021
Color	Black
Mileage	23721 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DIRTY MINOR DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	INNER RELACED HANDLE WORN OUT	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED,REFITTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS COVERED, CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR SHAKING, PARTS REFITTED	الحالة النظرية للمحرك
------------------------------	-------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
---------------------	------------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR JERKING	الحالة النظرية للجير
--------------------------------	---------------	----------------------

Condition	Remarks	الحالة
05.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	FRONT NOT WORKING	ازرع المساحات والشفرات
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES SIGN OF DRY CRACK	ازرع
09 Interior Condition		الحالة الداخليه
09.A AC Condition	OK	المكيف
09.B Roof Ceiling	PORTION MINOR LOOSE	بطانه السقف
09.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae