



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **03 Jul 2022, 15:48:17**  
 Transaction Number **87597829 (CC10006)** Queue Number **312309**



Chassis Number **1J4FA49S56P751365**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Jeep**  
 Model **Wrangler**  
 Model Year **2006**  
 Color **Black**  
 Mileage **107660 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Engine Condition</b> <span>المحرك</span>		
01.A Visual Engine Condition	OIL LEAK & REFITTED, MISFIRING	حالة المحرك النظري
01.B Smoke	BLACK SMOKE	دخان
<b>02 Transmission Condition</b> <span>الجير</span>		
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	REFITTED & LEAK	حالة الجير النظري
<b>03 Steering Condition</b> <span>المقود</span>		
03.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
03.B Other	STABILIZER LINK BOLT DAMAGED & BAR LOOSE	اخرى
<b>04 Suspension System</b> <span>ممتص الصدمات</span>		
04.A Arms	CONTROL ARM BUSHES CRACKED	ازرع
04.B Other	CONTROL BAR BOOT CUT	اخرى
<b>05 Body</b> <span>جسم المركبة</span>		
05.A Other	FRONT FENDER FRAME, WHEEL ARCH REPAIRED	اخرى
05.B Fenders	PORTION REPAIRED, REPAINTED, CRACKED	مدكار

DEFECT	REMARKS	
05.C Bonnet	PORTION REPAIRED, REPAINTED, PORTION FADED	غطاء المحرك
05.D Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES, PORTION FADED, PORTION RUSTY ON BODY	الصبغ
05.E Sign of front accident		وجود مؤشر لحادث في المقدمة
05.F Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
05.G Doors	REAR GLASS LOCK DAMAGED & LOOSE	أبواب
<b>06 Interior Condition</b>		<b>الحالة الداخلية</b>
06.A AC Condition	OK	المكيف
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHASSIS FRAME RUST PROOFED	الشاسيه
07.B Chassis Number	VIN NUMBER STICKER PORTION DAMAGED	رقم القاعدة
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.