



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **27 May 2023, 11:20:59**
 Transaction Number **33329961 (CC10013)** Queue Number **727428**



Chassis Number **JN1CC11C89T030803**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Tiida**
 Model Year **2009**
 Color **--**
 Mileage **262849 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	NOT CHECK GRILL PORTION CRACK	المكيف
01.B Other	GEAR LEVER KNOB WORN OUT	اخرى
01.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.D Dash Board	FUSE BOX COVER MISSING	لوحة القيادة
01.E Sun Visor	LEFT SIDE MISSING	حاجب الشمس
02 Engine Condition		المحرك
02.A Mount	MOUNT RUBBER CRACK	كرسي
02.B Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK OIL WET SUMB DENT REFITTED	حالة المحرك النظري
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	NOT CHECK MINOR OIL LEAK REFITTED	حالة الجير النظري
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	2016 EXPIRED CRACKED	الاطار الخلفي

DEFECT	REMARKS	
04.B Rims Condition	DENT SCRATCHES NUT MISSING OUTER HUB COVER MISSING	حالة الجنوط
04.C Front Tyre	2016 EXPIRED CRACKED	الاطار الامامي
05 Body		جسم المركبة
05.A Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
05.B Vehicle Color	GRAY	لون المركبة
05.C Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES PORTION RUSTY & FADED	الصبغ
05.D Trunk	NOT OPEN FOR CHECK	صندوق
05.E Bumper	MISALIGN PORTION CRACK	دعامية
05.F Other	FRONT BUMPER FRAME RADIATOR FRAME BULK HEAD BACK PANEL BOTH SIDE QUARTER PANEL REPAIRED	اخرى
05.G Floor	UNDER FLOOR MINOR DENT	الارضية
05.H Windshield	FRONT CRACK	زجاج
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSH CRACK	ازرع
06.B Shock Absorber	FRONT UPPER MOUNT RUBBER CRACK, REAR BOTH LEAK	ممتص الصدمات
06.C Ball Joint	BOOT CUT	مفصل كروي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE PORTION CRACK	الانارة
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Exhaust System		نظام العادم
09.A Other	CUT REWALDED	اخرى
10 Chassis Condition		الشاسي
10.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED DENT	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.