





Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18675103	Plate Category	: PRIVATE
Transaction Date	: 05 DEC 2019 12:52:17	Plate Number	: 3770 EA
Queue Number	: 122631	Import Doc. Ref.	:
Chassis Number	: WDB1714561F023770	Manufacturer/Model	: MERCEDES/SLK 350
Engine Number	:	Model Year	: 2006
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.02 - Tail Lights		الانوار الخلفية
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
02.13 - Stub Axle Assemblies, Boots		المحور
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصبغ
05.03 - Doors		الابواب
05.08 - Chassis (Frame)		الشاصية
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.13 - Exhaust System		نظام العادم
06.21 - Battery Condition		حالة البطارية
09 Auction		الفحص الكامل



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18675103	Plate Category	: PRIVATE
Transaction Date	: 05 DEC 2019 12:52:17	Plate Number	: 3770 EA
Queue Number	: 122631	Import Doc. Ref.	:
Chassis Number	: WDB1714561F023770	Manufacturer/Model	: MERCEDES/SLK 350
Engine Number	:	Model Year	: 2006
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.10 - Engine Oil Leaking	OIL LEAK	تهريب زيت المحرك
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		