



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Jan 2023, 12:12:06
Transaction Number	58155926 (CC10006)	Queue Number	657757



Chassis Number	JN1CC11CX6T100751
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Tiida
Model Year	2006
Color	Black
Mileage	310152 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2018/2014 EXPIRED ,CRACKED .	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018 EXPIRED ,CRACKED .	الاطار الخلفي
02 Body		جسم المركبة
02.A Floor	PORTION DENT .	الارضية
02.B Fenders	REAR LEFT SIDE DAMAGED .	مدكار
02.C Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY ,	صدأ
02.D Paint	BODY PORTION REPAIRED REPAINTED ,DENTS SCRATCHES ,PORTION FADED ,PORTION RUSTY ,	الصبغ
02.E Bumper	MISALIGN PORTION DAMAGE.	دعامية
02.F Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	اخرى
02.G Sign of side accident		وجود مؤشر لحادث في الجانب
02.H Sign of front accident		وجود مؤشر لحادث في المقدمة
03 Suspension System		ممتص الصدمات
03.A Arms	LOWER ARM BUSHES CUT ,	ازرع
03.B Shock Absorber	TOP MOUNT CUT ,LEAKING .	ممتص الصدمات

DEFECT	REMARKS	
04 Chassis Condition		الشاصي
04.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED.	الشاسيه
05 Lights		الاضاءة
05.A Head Light	LENS FADED .	الاضاءة الرئيسية
06 Interior Condition		الحاله الداخليه
06.A AC Condition	NO COOLING.	المكيف
06.B Dash Board	PORTION DAMAGED .	لوحة القيادة
06.C Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
07 Engine Condition		المحرك
07.A Mount	CRACKED ,	كرسي
07.B Visual Engine Condition	MINOR OIL LEAK REFITTED , JERKING	حالة المحرك النظري
07.C Smoke	WHITE SMOKE.	دخان
08 Steering Condition		المقود
08.A Steering Box	OIL LEAK .	جهاز المقود
09 Transmission Condition		الجير
09.A Road Test	NOT CHECKED .	فحص علي الطريق
09.B Visual Gear Box Condition	REFITTED OIL LEAK ,JERKING .	حالة الجير النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.