





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20081552	Plate Category	: PRIVATE
Transaction Date	: 29 JUN 2020 12:01:47	Plate Number	: 829037 EA
Queue Number	: 190664	Import Doc. Ref.	:
Chassis Number	: KMHJM81D18U829037	Manufacturer/Model	: HYUNDAI/TUCSON
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.01 - Side Lights		الانوار الجانبية
		FRONT LEFT PARK LIGHT NOT WORKING
01.04 - Head Lights		الانوار الامامية
		LENS FADED
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		DOT 1119-3618
04.07 - Rims		الرنجات
		CENTER CAP MISSING
05 Body		الهيكل
05.02 - Paint		الصنع
		DENT/SCRATCHES/FADED
05.05 - Bumpers		الدعامية
		BUMPER REPAIRED
05.07 - Floor		الارضية
		REAR DOOR & BACK PANEL REPAIRED
05.12 - Side Safety Frame		الواقبات الجانبية
		RADIATOR FRAME REPLACED
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة
		MANUAL MODE MALFUNCTION
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		ENGINE MISFIRES/CUT OFF/ROAD TEST NOT DONE
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		191621 KM
09 Auction		الفحص الكامل
09.06 - Chassis Ok		النشاصي جيد
		OK
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20081552	Plate Category	: PRIVATE
Transaction Date	: 29 JUN 2020 12:01:47	Plate Number	: 829037 EA
Queue Number	: 190664	Import Doc. Ref.	:
Chassis Number	: KMHJM81D18U829037	Manufacturer/Model	: HYUNDAI/TUCSON
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

#### Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTION REPAINTED	أثر صدىغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p>		