CAR CHECK

# شهادة فحص مركبة
# Vehicle Test Certificate

| | |
|---|---|
| Queue Number | 2906075 |
| Transaction Date | 30 Oct 2026, 14:53:31 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 19531580 (CC10010) (CC10011) |



## Vehicle Details

| | |
|---|---|
| Chassis Number | JN6FE52S06******* |
| Specification | GCC Specification |
| Make | Nissan |
| Model | Urvan |
| Model Year | 2006 |
| Color | White |
| Mileage | N/A NA |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | **جسم المركبة** |
| 01.A Fenders | REFITTED | مدكار |
| 01.B Paint | BODY REPAIRED REPAINTED,DENTS SCRATCHES,PORTION RUSTY FADED CRACKED | الصبغ |
| 01.C Doors | FRONT RIGHT SIDE REFITTED,REAR BOTH MISALIGN LEFT SIDE NOT OPEN | أبواب |
| 01.D Rusty | UNDER BODY SUSPENSION PARTS GETTING RUSTY. | صدأ |
| 01.E Floor | UNDER FLOORING RUNNING BOARD WHEEL ARCH REPAIRED, RUSTY HOLE WEK . | الارضية |
| 01.F Bumper | MISALIGN PORTION DAMAGED | دعامية |
| 01.G Pillars | RIGHT SIDE DOOR PILLAR ROCKER PANEL REPAIRED | القوائم |
| 01.H Trunk | NOT OPEN | صندوق |
| 01.I Sign of front accident | BUMPER FRAME ,FIREWALL COWL PANEL ,WHEEL ARCH REPAIRED. | وجود مؤشر لحادث في المقدمة |
| 01.J Sign of back accident | BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED. | وجود مؤشر لحادث في الخلف |
| **02 Chassis Condition** | | **الشاصي** |
| 02.A Chassis | FRONT CHASSIS ,CROSS MEMBER ,REAR CHASSIS BADLY REPAIRED DENT RUSTY BULGED . | الشاسيه |
| **03 Engine Condition** | | **المحرك** |
| 03.A Mount | BUSHES CUT . | كرسي |
| 03.B Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY | الحالة النظريه للمحرك |
| **04 Seats Condition** | | **المقاعد** |
| 04.A Seat Condition | PORTIO DAMAGED,REAR SEATS MISSING CABIN MODIFIED | حالة المقاعد |

| Condition | Remarks | الحالة |
|---|---|---|
| **05 Transmission Condition** | | **الجير** |
| 05.A Gear Box Visual Condition | REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED. | فحص علي الطريق |
| **06 Tires and Rims Condition** | | **الاطارات** |
| 06.A Front Tyre | BOTH SIDE 2022 CRACK WORN OUT | الاطار الامامي |
| 06.B Rear Tyre | BOTH SIDE 2022 CRACK WORN OUT | الاطار الخلفي |
| **07 Lights** | | **الاضاءة** |
| 07.A Head Light | LENS FADED PORTION CRACKED,ALL LIGHT NOT CHECK | الاضاءة الرئيسية |
| **08 Brake Condition** | | **الفرامل** |
| 08.A Disc&Drum | RUSTY. | دسك وطنابير الفرامل |
| **09 Suspension System** | | **ممتص الصدمات** |
| 09.A Shock Absorber | LEAK . | ممتص الصدمات |
| 09.B Leaf Spring | BUSHES CUT . | |
| 09.C Arms | BUSHES CUT . | ازرع |
| 09.D Stabilizer Bar And Link Rod | BUSHES CUT . | عمود التوازن و مثبت عمود التوازن |
| **10 Steering Condition** | | **المقود** |
| 10.A Steering Boot | CUT . | ربلة المقود |
| 10.B Steering Box | OIL LEAK | جهاز المقود |
| 10.C Tie Rod End | BALL JOINT BOOT CUT . | مؤخرة الرودات |
| **11 Interior Condition** | | **الحاله الداخليه** |
| 11.A Other | INTERIOR PARTS RUSTY DUSTY/,SIGN OF FLOODED | اخري |
| 11.B Mirror | CENTER MISSING | المرايا |
| 11.C AC Condition | NOT CHECK GRILL PORTION DAMAGED | المكيف |
| 11.D FLoor Matting | DAMAGED | فرش الأرضيه |
| 11.E Dash Board | PORTION DAMAGED | لوحة القياده |
| 11.F Odometer reading | NOT CHECK | قراءة عداد المسافات |
| 11.G Door Panel | PORTION DAMAGED | لوحة بطانة الباب |
| 11.H Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 11.I Gear Shifting Lever | KNOB WORN OUT,DUST COVER DAMAGED | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**