





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20485291	Plate Category	: PRIVATE
Transaction Date	: 05 AUG 2020 11:53:08	Plate Number	: 251996 EA
Queue Number	: 203029	Import Doc. Ref.	:
Chassis Number	: 3N1BC1A60CK251996	Manufacturer/Model	: NISSAN/TIIDA
Engine Number	:	Model Year	: 2012
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.06 - Brake Lights		انوار الفرامل BRAKE LIGHT SWITCH DEFECTIVE
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.16 - Engine Mounting		كراسي المحرك UPPER MOUNTING CRACK
03 Brake System		نظام الفرامل
03.05 - Brake Pedal		حواصة الفرامل BRAKE PEDAL HARD /BRAKE WEAK ROAD TEST NOT DONE
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية ALL TIRES CRACKS
04.08 - Spare Tires		الاطار الاحتياطي MISSING
05 Body		الهيكل
05.02 - Paint		الصبغ BODY SCRATCH & DENT
05.04 - Fenders		المدكار FRONT BOTH SIDE FENDER FRAME REPAIRED
05.05 - Bumpers		الدعامية REAR BUMPER SCRATCH & MISALIGN & FRONT REPLACED /FRONT BUMPER SUPPORT & CRASH BOX REFITTED
05.07 - Floor		الارضية BACK PANEL DENT
05.08 - Chassis (Frame)		الشاصية FRONT BOTH SIDE FRAME MEMBER END REPAIRED & DENT
05.12 - Side Safety Frame		الواقيات الجانبية BULKHEAD & RADIATOR SUPPORT REPAIRED
06 General Items		الاشياء العامة
06.20 - Fuel Tank		خزان الوقود FUEL TANK LEAK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى 177059 KM BONNET & FRONT BOTH SIDE FENDERS REPLACED



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20485291	Plate Category	: PRIVATE
Transaction Date	: 05 AUG 2020 11:53:08	Plate Number	: 251996 EA
Queue Number	: 203029	Import Doc. Ref.	:
Chassis Number	: 3N1BC1A60CK251996	Manufacturer/Model	: NISSAN/TIIDA
Engine Number	:	Model Year	: 2012
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09 Auction		الفحص الكامل
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.18 - A/C Not Cooling		عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	AIR BAG LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTION REPAINTED	أثر صنع في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		

Test Certificate



FAILED

Change possession :	62517347	
Chassis No :	3N1BC1A60CK251996	
Vehicle Make :	NISSAN	
Vehicle Model :	TIIDA	
Vehicle Class :	Light Vehicle	
Body Type :	SALOON	
Fuel :	Benzene	
Color :	White	
Drive Direction :	Left Hand Side	
Dimensions : (H x W x L) -- x -- x --		
Current Odometer :	177059 Kms.	
Origin :	Mexico	Model Year :
Gear Type :	Automatic	2012
Engine No :	MR1887229...	Engine Size :
Axles No :	2	3500 CC
No Of Doors :	4	Horse Power :
G. V. W. :	1750 Kgs.	123
		Cylinders :
		4
		No Of Seats :
		5
		Empty Weight :
		1111 Kgs.

Certificate Number :	5-TAS-2020-12305102
Inspection Date :	09-08-2020
Certificate Print Date :	09-08-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	15 min 35 sec
Appointment Ref Number :	--
Start Time :	End Time :
12:07	12:23
Lane :	Token No. :
01	6
Attempt :	Prints No. :
1	1

Parameter Readings

Service brake imbalance on front axle 14 %	Service brake imbalance on rear axle 21 %	Parking brake imbalance between LHS and RHS 9 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 15 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Stop lamps repair brake light switch defective	Always on	Major
Fuel tank and pipings fuel tank leak	Leaking	Major
Pedal brake pedal very hard	Hard/spongy	Major
Tire change all 4 tires cracks & old	Others (Major)	Major
Spare Tire	Missing (Major)	Major
Warning triangle	Missing	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	1800	

Inspection Remarks: FRONT BOTH SIDE FRAME MEMBER END REPAIRED & DENT BULKHEAD & RADIATOR SUPPORT REPAIRED