



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 May 2023, 12:06:04
Transaction Number	68742509 (CC10010)	Queue Number	716168



Chassis Number	MR2BW9F36E1007011
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Yaris
Model Year	2014
Color	--
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Sign of front accident		وجود مؤشر لحادث في المقدمة
01.B Bumper	MISALIGN ,PORTION DAMAGE.	دعامية
01.C Sign of back accident		وجود مؤشر لحادث في الخلف
01.D Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED & REAR BUMPER FRAME ,BACK PANEL ,QUARTER PANEL COMPARTMENT REPAIRED.	اخرى
01.E Bonnet	REFITTED ,REPAIRED ,	غطاء المحرك
01.F Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
01.G Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES ,PORTION FADED ,PORTION RUSTY	الصبغ
01.H Fenders	REFITTED ,REPAIRED.	مدكار
01.I Floor	RUNNING BOARD DENT ,PORTION DAMAGE, HOLE.	الارضية
01.J Vehicle Color	WHITE.	لون المركبة
01.K Trunk	REPAIRED REFITTED . ALWAYS OPEN.	صندوق
<b>02 Suspension System</b>		<b>ممتص الصدمات</b>
02.A Arms	LOWER ARM BUSHES CRACKED .	ازرع
02.B Shock Absorber	LEAK,WEAK.	ممتص الصدمات

DEFECT	REMARKS	
02.C Coil Spring	REAR BOTH SIDE MISSING, BODY LEVEL VERY LOW.	ياي حلزوني
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	DAMAGE .	الاطار الامامي
03.B Rear Tyre	DAMAGE .	الاطار الخلفي
<b>04 Interior Condition</b>		<b>الحالة الداخلية</b>
04.A Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
04.B Door Panel	LOOSE PORITON DAMAGE .	لوحة بطانة الباب
04.C AC Condition	NOT CHECKED .	المكيف
04.D Dash Board	GLOVE BOX DAMAGE .	لوحة القيادة
04.E Audio	DISPLAY MELTED.	صوتيات
04.F Odometer reading	NOT CHECKED .	قراءة عداد المسافات
04.G Other	CENTER CONSOLE LOOSE.	اخرى
04.H Roof Ceiling	PORTION LOOSE.	بطانه السقف
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Visual Gear Box Condition	NOT CHECKED ,REFITTED OIL LEAK.	حالة الجير النظري
05.B Road Test	NOT CHECKED .	فحص علي الطريق
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED .OIL LEAK.	حالة المحرك النظري
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Axle	BOOT CRACK.	اكسلات
08.B Steering Boot	CUT.	ربلة المقود
08.C Steering Box	OIL LEAK.	جهاز المقود
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	FRONT RIGHT SIDE CHASSIS FLOOR REINFORCEMENT AREA CRACKED, HOLE,DENT.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

fitness for registration.