



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **16 May 2023, 12:53:36**  
 Transaction Number **94269945 (CC10006)** Queue Number **716301**



Chassis Number **LMGKT1G58P1132543**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **GAC**  
 Model  
 Model Year **2020**  
 Color **White**  
 Mileage **16187 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.B Vehicle Model	GN 6	طراز المركبة
01.C Paint	BODY MINOR DENT, SCRATCHES,	الصبغ
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	OK	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	OK	حالة المحرك النظري
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	OK	حالة الجير النظري
<b>05 Interior Condition</b>		<b>الحاله الداخليه</b>
05.A AC Condition	OK	المكيف
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2021,	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.