



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>05 Dec 2022, 10:31:42</b>
Transaction Number	<b>71187014 (CC10009)</b>	Queue Number	<b>635709</b>



Chassis Number	<b>WAUZZZ8R79A034428</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Audi</b>
Model	<b>Q5</b>
Model Year	<b>2008</b>
Color	<b>White</b>
Mileage	<b>001 Miles</b>
Fuel Type	<b>Diesel</b>
No. Of Cylinders	<b>4</b>
Specification	<b>Imported</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
01.B Visual Gear Box Condition	NOT CHECKED , REFITTED	حالة الجير النظرى
01.C Road Test	NOT CHECKED	فحص علي الطريق
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	NOT CHECKED	المكيف
02.B Dash Board	PORTION DAMAGED	لوحة القيادة
02.C Other	RIGHT SIDE CONSOLE BOX DAMAGED	اخرى
02.D Odometer reading	NOT CHECKED	قراءة عداد المسافات
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED & MUDDY CHECKED VISIBLE AREA ONLY	الارضية
03.B Vehicle Year Model	AS PER CHASSIS NUMBER YEAR MODEL 2009	سنة صنع المركبة
03.C Paint	BODY MMINOR DENT,SCRATCHES,	الصبغ
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي

DEFECT	REMARKS	
04.B Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis Number	MANUFACTUR STICKER MISSING, VIN CHECKED ON APRON AREA ONLY	رقم القاعدة
05.B Chassis	FRONT RIGHT SIDE CHASSIS REAINFORCMENT AREA DENT	الشاسيه
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSHES CUT	ازرع
06.B Shock Absorber	LEAK	ممتص الصدمات
06.C Ball Joint	BOOT CUT	مفصل كروي
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.B Axle	RIGHT SIDE AXLE DAMAGED	اكسلات
07.C Steering Oil	OIL LEAK	زيت المقود
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,PARTS MISSING. OIL LEAK REFITTED	حالة المحرك النظري
08.B Mount	MOUNT RUBBER CUT	كرسي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.