

Queue Number 2800853

Transaction Date 25 Sep 2026, 10:13:47

Site Name
840 - Emirates AuctionsTransaction Number
75057727 (CC10013) (CC10013)

Vehicle Details

Chassis Number LS5A3DKR1P*****
 Specification GCC Specification
 Make Changan
 Model CS 35
 Model Year 2023
 Color Blue
 Mileage 44362 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	BODY MINOR DENT SCRATCHES PORTION GETTING FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY	الارضية
01.D Bumper	MISALIGN PORTION SCRATCHES	دعامية

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسية
--------------	--	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	OIL WET , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	-------------------------------	-----------------------

04 Transmission Condition	الجير
---------------------------	-------

04.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	-------------------------------------	----------------------

04.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

05 Tires and Rims Condition	الاطارات
-----------------------------	----------

05.A Front Tyre	2020 DRY CRACK	الاطار الامامي
05.B Rear Tyre	2020 DRY CRACK	الاطار الخلفي

06 Lights	الاضاءة
-----------	---------

Condition	Remarks	الحالة
06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Dash Board	GETTING FADED	لوحة القيادة
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae