

Queue Number

2865661

Transaction Date

13 Oct 2026, 16:18:48

Site Name

840 - Emirates Auctions

Transaction Number

14342346 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JTDBW92358*****
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2008
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED , DENT SCRATCHES, GETTING RUSTY HOLE	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR , RUNNING BOARD MINOR DENT , MUDDY	الارضية
01.F Bumper	FRONT BUMPER MISALIGN , TOW HOOK COVER MISSING & REAR BUMPER BADLY DAMAGE	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE B/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Sign of front accident	BUMPER FRAME , INNER FENDER FRAME , RADIATOR SUPPORT REPAIRED , DENT	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED , DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY , OILY MUDDY	الشاسيه
--------------	------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECK , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظرية للجير
--------------------------------	--	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2021 & RIGHT SIDE 2019 CRACK EXPIRED	الاطار الخلفي
05.C Rims Condition	DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Interior Condition		الحالة الداخلية
07.A Other	CENTER CONSOLE BOX COVER , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
07.B Mirror	LEFT SIDE MIRROR LOOSE	المرايا
07.C AC Condition	NOT CHECK , CONTROL PANEL PORTION WORN OUT	المكيف
07.D Power Window Switch And Glass	ADJUSTABLE LEVER LOOSE (MANUAL)	مفتاح النافذه و الزجاج
07.E Floor Matting	DIRTY	فرش الأرضيه
07.F Audio	CONTROL PANEL BUTTON PORTION WORN OUT	صوتيات
07.G Dash Board	PORTION WORN OUT , FUSE BOX COVER MISSING	لوحة القيادة
07.H Roof Ceiling	FABRIC WORN OUT	بطانه السقف
07.I Sun Visor	LEFT SIDE LOOSE	حاجب الشمس
07.J Odometer reading	CLUSTER DISPLAY PANEL PORTION FADED	قراءة عداد المسافات
07.K Door Panel	WORN OUT	لوحة بطانة الباب
07.L Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.M Gear Shifting Lever	WORN OUT	ذراع نقل السرعات
08 Engine Cooling System		نظام تبريد المحرك
08.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

للشكاوي والمقترحات يمكنك التواصل معنا عبر

