

Queue Number

2830559

Transaction Date

03 Oct 2026, 13:01:08

Site Name

840 - Emirates Auctions

Transaction Number

73944280 (CC10010) (CC10010)



Vehicle Details

Chassis Number	4T1BB46K17*****
Specification	Imported
Make	Toyota
Model	Camry
Model Year	2007
Color	--
Mileage	N/A NA
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE FRONT REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA ,	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Windshield	FRONT SPOT CRACKED .	زجاج
01.G Roof	REPAINTED.	السقف
01.H Bonnet	REFITTED ,HINCH REPAIRED.	غطاء المحرك
01.I Trunk	NOT CLOSING.	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident	RIGHT SIDE FLOORING RUNNING BOARD,ROCKER PANEL REPAIRED.	وجود مؤشر لحادث في الجانب
01.L Vehicle Color	GREEN	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS END REPAIRED DENT ,REAR EXTENSION JOINT AREA GETTING RUSTY ,FRONT COVERED ,CHECKED ONLY VISIBLE AREA ,	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY DOOR POST STICKER.	رقم القاعدة

Condition	Remarks	الحالة
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	EXPIRED CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	EXPIRED CRACKED WORN OUT PUNCTURE.	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES.	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
06.B Tail Light	PORTION CRACKED .	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
10.B Mirror	LOOSE,FADE.	المرايا
10.C Floor Matting	EXTRA MATTING.	فرش الأرضيه
10.D Dash Board	LEATHER REPLACED PORTION LOOSE.	لوحة القيادة
10.E Roof Ceiling	PORTION LOOSE. RIGHT SIDE GRAB HANDLE MISSING.	بطانه السقف
10.F Sun Visor	PORTION LOOSE.	حاجب الشمس
10.G Odometer reading	NOT CHECKED .	قراءة عداد المسافات
10.H Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.J Gear Shifting Lever	KNOB WORN OUT PORTION CUT .	ذراع نقل السرعات



Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae