



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **24 May 2023, 12:32:04**
 Transaction Number **91714780 (CC10013)** Queue Number **724319**



Chassis Number **JN1CA31C64T736727**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Maxima**
 Model Year **2004**
 Color **Grey**
 Mileage **343547 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

| DEFECT | REMARKS | |
|---|---|----------------------------|
| 01 Transmission Condition | | الجير |
| 01.A Road Test | NOT CHECK | فحص علي الطريق |
| 01.B Visual Gear Box Condition | NOT CHECK | حالة الجير النظري |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Rear Tyre | CRACKED DAMAGED | الاطار الخلفي |
| 02.B Front Tyre | CRACKED DAMAGED | الاطار الامامي |
| 03 Interior Condition | | الحاله الداخليه |
| 03.A Door Panel | PORTION WORN OUT | لوحة بطانة الباب |
| 03.B AC Condition | NOT CHECK | المكيف |
| 03.C Other | CONSOLE BOX PORTION DAMADED | اخرى |
| 03.D Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 04 Body | | جسم المركبة |
| 04.A Paint | BODY PORTION REPAINTED PORTION REPAIRED PORTION RUSTY & FADED MNOR DENT SCRATCHES | الصبغ |
| 04.B Bumper | MISALIGN FADED PORTION CRACK | دعامية |

| DEFECT | REMARKS | |
|------------------------------|--|---------------------|
| 04.C Other | VISUAL TEST ONLY | اخرى |
| 04.D Floor | UNDER FLOOR CHASSIS SUSPENSION PARTS NOT CHECK | الارضية |
| 05 Brake Condition | | الفرامل |
| 05.A Disc&Drum | RUSTY | دسك وطنابير الفرامل |
| 06 Chassis Condition | | الشاصي |
| 06.A Chassis | NOT CHECK | الشاسيه |
| 07 Lights | | الاضاءة |
| 07.A Tail Light | LEFT SIDE CRACK | الانارة |
| 08 Engine Condition | | المحرك |
| 08.A Visual Engine Condition | ENGINE NOT START ALL SYSTEM NOT CHECK | حالة المحرك النظري |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.