

Queue Number 2810804

Transaction Date 28 Sep 2026, 16:55:18

Site Name
840 - Emirates AuctionsTransaction Number
36574968 (CC10021) (CC10025)

Vehicle Details

Chassis Number	JTJHT00W42*****
Specification	Imported
Make	Lexus
Model	LX 470
Model Year	2002
Color	Black
Mileage	379058 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED , PORTION GETTING RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR GETTING RUSTY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGED	دعامية
01.E Trunk	MINOR LOOSE , MISALIGN	صندوق
01.F Sign of front accident	BUMPER FRAME,FENDER FRAME,RADIATOR FRAME SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME GETTING RUSTY,BULGED,PORTION DENT	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED,OIL LEAK,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT ADJUSTMENT COVER PORTION MISSING , BACK COVER PORTION LOOSE , REAR BOTH SIDE HEAD REST PORTION MISSING , REAR MISSING	حالة المقاعد
---------------------	--	--------------

05 Exhaust System

نظام العادم

05.A Other	CUT & REWELDED	اخرى
------------	----------------	------

06 Transmission Condition

الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	REFITTED,OIL LEAK,PARTS GETTING RUSTY,JERKING	الحالة النظرية للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2024 , RIGHT SIDE 2023	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES , FRONT LEFT SIDE NUT MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED , BRACKET DAMAGED	الاضاءة الرئيسية
08.B Warning Light	WORNING LIGHT ON DISPLAY	ضوء تحذير
08.C Brake Light	CENTER COVER PORTION CRACK	نور الفرامل
08.D Fog light	NOT WORKING	كشاف الضباب
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY WEAK,NOT WORKING PROPERLY	دواسة الفرامل
09.B Disc&Drum	RUSTY	دسك وطناير الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES CRACK	ازرع
10.B Ball Joint	BOOT CUT	مفصل كروي
10.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10.D Hydraulic System	NOT WORKING	النظام الهيدروليكي
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED	اخرى
11.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING	المرآيا
11.C AC Condition	NOT COOLING , GRILL PORTION LOOSE , SWITCH PORTION FADED , REAR GRILL DAMAGED	المكيف
11.D Roof Light	REAR NOT WORKING PROPERLY	أنارة السقف
11.E Power Window Switch And Glass	REAR RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.F Audio	SCREEN FADED	صوتيات
11.G Dash Board	WORN OUT , PORTION LOOSE	لوحة القيادة
11.H Door Panel	WORN OUT	لوحة بطانة الباب
11.I Steering Wheel and control buttons	WORN OUT,HAVE PLAY	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae