



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	30 Dec 2021, 17:51:35
Transaction Number	96477501 (CC10006)	Queue Number	312309



Chassis Number	JTFLJ73J646020013
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	2004
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Steering Wheel and control buttons	STEERING LOWER COVER MISSING	عجلة القيادة وازرار التحكم
01.B Odometer reading	NOT CHECK	قراءة عداد المسافات
01.C AC Condition	NOT CHECK	المكيف
02 Seats Condition		المقاعد
02.A Seat Belt	OK	حزام الأمان
02.B Seat Condition	SEAT DAMAGED	حالة المقاعد
03 Engine Condition		المحرك
03.A Engine Condition	OIL LEAK&ENGINE NOT START ALL SYSTEM NOT CHECK	حالة المحرك
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OIL LEAK& NOT CHECK	الجير
04.C DIFFERENTIAL	FRONT DIFFERENTIAL LEAK	الدفرنشيل
05 Body		جسم المركبة
05.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,RUSTY	الصبغ

DEFECT	REMARKS	
05.B Rusty	UNDER BODY PARTS, SUSPENSION ,CHASSIS ,FLOOR RUSTY	صدأ
05.C Fenders	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
05.D Doors	LEFT SIDE DOOR , DOOR PILLAR REPAINTED,PORTION REPAIRED & RIGHT SIDE DOOR & DOOR PILLAR REPAINTED	أبواب
05.E Roof	REPAINTED,PORTION REPAIRED,PORTION RUSTY	السقف
05.F Floor	REAR CARRIOR BOX REPAINTED,PORTION REPAIRED	الارضية
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2017 CRACKED ,WORN OUT	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2017 CRACKED & RIGHT SIDE 2019	الاطار الخلفي
06.C Rims Condition	RIMS HAVE MINOR SCRATCHES & FRONT & REAR BOTH SIDE WHEEL HUB COVER MISSING	حالة الجنوط
06.D Spare Tire &Tools	SPARE TIRE&TOOLS MISSING	الاطار الاحتياطي و العدة
07 Chassis Condition		الشاسي
07.A Chassis	CHASSIS FRAME RUSTY	الشاسيه
08 Lights		الاضاءة
08.A Fog light	LEFT SIDE DAMAGED	كشاف الضباب
08.B Tail Light	REAR LEFT SIDE LOOSE	الانارة
08.C Head Light	ALL LIGHT NOT CHECK	الاضاءة الرئيسية
09 Wipers and Arms		المساحات
09.A Wiper Arm &Blade	NOT CHECK	ازرع المساحات والشفرات
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود
11 Exhaust System		نظام العادم
11.A Other	EXHAUST BROKEN	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.