CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877713
Transaction Date	16 Oct 2026, 16:15:45
Site Name	840 - Emirates Auctions
Transaction Number	12631167 (CC10010) (CC10010)



Vehicle Details

Chassis Number	3N1BC1C79C*******
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2012
Color	White
Mileage	194678 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REFITTED.	مدكار
01.B Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENT .	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED .	غطاء المحرك
01.G Sign of back accident	BACK PANEL ,QUARTER PANEL ,SPARE WHEEL HOUSING REPAIRED,DENT .	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION REPAIRED DENT,FRONT CHASSIS END CROSS MEMBER DENT.	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,OIL PAN DENT ,	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
06.B Tail Light	PORTION CRACKED.	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
09.B AC Condition	NOT CHECKED .	المكيف
09.C Dash Board	PORTION LOOSE.	لوحة القياده
09.D Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae