



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **16 May 2023, 12:55:21**  
 Transaction Number **60981457 (CC10010)** Queue Number **716313**



Chassis Number **KNAPB8127D7416726**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Kia**  
 Model **Sportage**  
 Model Year **2013**  
 Color **White**  
 Mileage **264476 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Steering Condition</b>		<b>المقود</b>
01.A Axle	BOOT CUT.	اكسلات
01.B Steering Box	OIL LEAK.	جهاز المقود
01.C Steering Boot	CUT,	ربلة المقود
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	REFITTED OIL LEAK ,JERKING ,ABNORMAL NOISY.	حالة المحرك النظري
02.B Smoke	MINOR BLACK SMOKE.	دخان
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Bonnet	REFITTED ,REPAINTED.	غطاء المحرك
03.B Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES ,PORTION FADED ,PORTION RUSTY	الصبغ
03.C Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
03.D Floor	PORTION DENT .	الارضية
03.E Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	اخرى
03.F Doors	RIGHT SIDE REPAINTED ,PORTION REPAIRED. .	أبواب
03.G Bumper	MISALIGN ,PORTION DAMAGE.	دعامية

DEFECT	REMARKS	
03.H Sign of front accident		وجود مؤشر لحادث في المقدمة
03.I Fenders	REFITTED,REPAINTED.RER RIGHT SIDE QUARTER PANEL REPAIRED ,REPAINTED.	مدكار
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Seat Condition	PORTION DAMAGE.	حالة المقاعد
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Rear Tyre	BOTH SIDE 2021 CRACKED.	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2021 CRACKED.	الاطار الامامي
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	CHECKED ONLY VISIBLE AREA OK.	الشاسيه
<b>07 Interior Condition</b>		<b>الحاله الداخليه</b>
07.A AC Condition	NO COOLING.	المكيف
07.B Steering Wheel and control buttons	WORN OUT ,CRACKED .	عجلة القيادة وازرار التحكم
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	LOWER ARM BUSHES CRACKED .	ازرع
<b>09 Transmission Condition</b>		<b>الجير</b>
09.A Visual Gear Box Condition	,REFITTED OIL LEAK.	حالة الجير النظري
09.B Road Test	NOT CHECKED.	فحص علي الطريق
<b>10 Lights</b>		<b>الاضاءة</b>
10.A Tail Light	CRACKED.	الانارة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.