

Queue Number

2761296

Transaction Date

18 Sep 2026, 16:33:03

Site Name

840 - Emirates Auctions

Transaction Number

86232605 (CC10010) (CC10011)



Vehicle Details

Chassis Number	WAUZZZF84L*****
Specification	GCC Specification
Make	Audi
Model	A8
Model Year	2020
Color	Black
Mileage	18616 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH,REAR LEFT SIDE REPAINTED PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED,FRONT RIGHT SIDE PORTION REPAIRED REPAINTED,REAR LEFT REFITTED	أبواب
01.D Floor	UNDER FLOOR COVERED PORTION CUT .	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.F Windshield	REAR CURTAIN DAMAGED ,EXTRA STICKER.	زجاج
01.G Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE C/ PILLAR ROCKER PANEL REPAIRED.	القوائم
01.I Trunk	REPAINTED MISALIGN,AUTO NOT WORKING PROPERLY	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب
01.L Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED.	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS & REAR LEFT SIDE CHASSIS EXTENSION REPAIRED PORTION BULGED DENT.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER .	رقم القاعدة

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Smoke	BLACK	دخان
03.B Other	OVER HEAT /SIGN OF BURNED.	اخرى
03.C Engine Visual Condition	ABNORMAL NOISY ,OIL LEAK,COOLANT MIXED WITH ENGINE OIL. OPEN REFITTED SHAKING GETTING RUSTY , DELAY STARTING, POOR ACCELERATION, WIRING OPEN LOOSE.	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	FRONT LEFT SIDE NOT WORKING , FRONT RIGHT SIDE LOOSE , REAR NOT WORKING.	حزام الأمان
04.B Seat Condition	BOTH SIDE ADJUSTMENT NOT WORKING.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK REFITTED GETTING RUSTY JERKING, DELAY SHIFTING.	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRARTCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Other	WIRING KIT DAMAGED , LOOSE ,UNSECURE .	اخرى
07.B Warning Light	EXTRA WARNING LIGHT & WARNING MESSAGE ON IN CLUSTER.	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY/	دواسة الفرامل
08.B Other	FAULT	اخرى
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	FRONT CROSS MEMBER SUBFRAME REPAIRED CRACKED	ممتص الصدمات ازرع اخرى النظام الهيدروليكي
09.B Shock Absorber	BODY LEVEL TOO LOW	
09.C Arms	BUSHES CRACKED .	
09.D Other	SUSPENSION PARTS CREFITTED .	
09.E Hydraulic System	AIR SUSPENSION NOT WORKING.	
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY ,MUDDY ,SIGN OF WATER FLOODED	اخرى
10.B AC Condition	NOT WORKING/.	المكيف
10.C Floor Matting	DIRTY MUDDY.	فرش الأرضيه
10.D Audio	NOT WORKING , SCREEN NOT WORKING & REAR BOTH SIDE LCD MISSING.	صوتيات
10.E Dash Board	REFITTED , LEATHER REPLACED	لوحة القيادة
10.F Air Bag	OPEN REFITTED .	وسائد هوائية
10.G Sunroof	NOT WORKING PROPERLY , GLASS PORTION CRACK , CURTAIN LOOSE , REAR NOT WORKING.	فتحت سقف
11 Engine Cooling System		نظام تبريد المحرك

Condition	Remarks	الحالة
11.A Coolant tank	OIL MIXED WITH COOLANT , LEAKING FROM TANK SIDE,	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae