



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Mar 2023, 13:02:18
Transaction Number	46577170 (CC10009)	Queue Number	686709



Chassis Number	WDDWF4CB0GR099217
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	C 200
Model Year	2016
Color	White
Mileage	212124 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
01.C Gear Box Mount	MOUNT RUBBER CRACK	كرسي الجير
01.D DIFFERENTIAL	SIGN OF MINOR OIL WET	الدفرنشل
02 Interior Condition		الحاله الداخليه
02.A AC Condition	OK	المكيف
02.B Steering Wheel and control buttons	MINOR WORN OUT	عجلة القيادة وازرار التحكم
02.C Sunroof	NOT WORKING	فتحت سقف
02.D Power Window Switch	MAIN SWITCH BUTTON LOOSE	مفتاح النافذه
02.E Roof Ceiling	PORTION LOOSE	بطانه السقف
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020 & MINOR WORN OUT	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
03.C Rims Condition	DENT SCRATCHES	حالة الجنوط

DEFECT	REMARKS	
04 Body		جسم المركبة
04.A Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT ,SCRATCHES	الصبغ
04.B Sign of front accident		وجود مؤشر لحادث في المقدمة
04.C Other	FRONT ASSEMBLY REFITTED	اخرى
04.D Bumper	MISALIGN , SCRATCHES	دعامية
04.E Floor	UNDER FLOOR PORTION COVERED, CHECKED VISIBLE AREA ONLY/OK	الارضية
04.F Fenders	REAR RIGHT SIDE FENDER PORTION REPAIRED , REPAINTED, FRONT REFITTED	مدكار
04.G Doors	FRONT RIGHT SIDE DOOR PORTION REPAINTED , REPAIRED	أبواب
04.H Sign of side accident		وجود مؤشر لحادث في الجانب
05 Suspension System		ممتص الصدمات
05.A Arms	LOWER ARM BUSH CRACK	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
07 Chassis Condition		الشاسي
07.A Chassis	CHASSIS FULLY COVERD CHECKED VISIBLE AREA ONLY/OK	الشاسيه
08 Engine Condition		المحرك
08.A Visual Engine Condition	ABNORMAL NOISY	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.