CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877806
Transaction Date	23 Oct 2026, 15:29:00
Site Name	840 - Emirates Auctions
Transaction Number	80850242 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WP1ZZZ92ZE*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2014
Color	Black
Mileage	143460 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAIRED REFITTED REPAINTED ,REAR RIGHT SDE REPAINTED ,	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.C Doors	BOTH SIDE DOORS REPAINTED REPAIRED ,FRONT RIGHT SIDE DAMAGED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN SCRATCHES BACK COVER MISSING.	دعامية
01.G Bonnet	REPAIRED REPAINTED REFITTED. STAY SHOCK MISSING	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY ,NOT VISIBLE PROPERLY ,CHECEKD ONLY VISIBLE AREA,PORTION DENT .	الشاسيه
02.B Other	STEAM WASH CHASSIS REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION DAMAGED LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED .	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	WEAK BODY LEVEL VERY LOW.	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	IMTERIOR PARTS GETTING RUSTY.	اخري
10.B AC Condition	NOT CHECKED.	المكيف
10.C Power Window Switch And Glass	FRONT LEFT MAIN SWITCH LOOSE MISSING.	مفتاح النافذه و الزجاج
10.D Dash Board	PORTION LOOSE.	لوحة القياده
10.E Door Panel	WORN OUT PORTION LOOSE ,PORTION CUT .	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.