CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2923744
Transaction Date	30 Oct 2026, 16:56:11
Site Name	840 - Emirates Auctions
Transaction Number	64631691 (CC10013) (CC10019)



Vehicle Details

Chassis Number	SALLSAAE4A*******
Specification	GCC Specification
Make	Range Rover
Model	Sport
Model Year	2010
Color	Gold
Mileage	135362 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED ,PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED ,PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Windshield	FRONT SPOT CRACKED	زجاج
01.H Fuel Tank	COVER DENT	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN LAMINATED NOT VISIBLE TO CHECK / CHECK ONLY DOOR POST STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DIAPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES MINOR DRY CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B Mirror	LEFT SIDE FOLDING NOT WORKING,LOOSE	المرايا
09.C AC Condition	OK	المكيف
09.D Roof Ceiling	LOOSE	بطانه السقف
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae