CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945081
Transaction Date	04 Nov 2026, 14:25:26
Site Name	840 - Emirates Auctions
Transaction Number	34960919 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTFHX02P06*******
Specification	GCC Specification
Make	Toyota
Model	Hiace
Model Year	2006
Color	White
Mileage	821565 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS BADLY RUSTY.	صدأ
01.C Floor	UNDER FLOOR WHEEL ARCH RUNNING BOARD BADLY RUSTY HOLE WEAK ,	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Pillars	DOOR POST PILLAR OUTER PANEL REPAIRED	القوائم
01.F Fuel Tank	DENT	خزان الوقود
01.G Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION REPAIRED DENT GETTING RUSTY .	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي
03.B Smoke	BLACK	دخان
03.C Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED OIL LEAK , ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED. .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025.	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Leaf Spring	BUSHES CRACKED.	
08.C Stabilizer Bar And Link Rod	BUSHES CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Boot	CUT	ربلة المقود
09.B Steering Box	OIL LEAK	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B Mirror	LOOSE FADED.	المرايا
10.C AC Condition	NOT COOLING.	المكيف
10.D Dash Board	GLOVE BOX DAMAGED .	لوحة القياده
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae