

Queue Number 2881640

Transaction Date 17 Oct 2026, 12:36:36

Site Name
840 - Emirates AuctionsTransaction Number
11536142 (CC10008) (CC10025)

Vehicle Details

Chassis Number	JN8AE2KPXE*****
Specification	Imported
Make	Nissan
Model	Quest
Model Year	2014
Color	Grey
Mileage	195106 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE & FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED MINOR DENTS SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	PORTION RUSTY	الارضية
01.F Roof	ROOF RACK RAIL MISSING	السقف
01.G Bonnet	PORTION DENT	غطاء المحرك
01.H Other	LET SIDE SLIDING DOOR ROCKER PANEL COVER PORTION DAMAGED	اخرى
01.I Trunk	REPAINTED PORTION REPAIRED , SWITCH MELTED	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME ,BULKHEAD REPAIRED.	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED DENT .	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	REAR CHASSIS EXTENSION END REPAIRED ,CHASSIS RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	-------------	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	REAR MISSING,DRIVER SEAT PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 EXPIRED CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIERD	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT SHOW IN DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	UNDER SEAT INTERIOR METAL PARTS RUSTY,SIGN OF FLOODED.	اخرى
09.B AC Condition	NOT WORKING	المكيف
09.C Dash Board	AIR BAG AREA PORTION CRACK	لوحة القيادة
09.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	GETTING WORN OUT , LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae