

Queue Number 2858864

Transaction Date 12 Oct 2026, 16:47:16

Site Name
840 - Emirates AuctionsTransaction Number
35512252 (CC10013) (CC10011)

Vehicle Details

Chassis Number	SALKA9BU5P*****
Specification	GCC Specification
Make	Range Rover
Model	HSE
Model Year	2023
Color	White
Mileage	151843 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE PORTION REPAIRED REPAINTED, REAR RIGHT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED, REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR FULLY COVERED FOR FULL INSPECTION REMOVE INNER FENDER UNDER ENGINE COVER FOR RECHECK	الارضية
01.F Bumper	MISALIGN, PORTION CRACK BULGE	دعامية
01.G Trunk	AUTO NOT WORKING PROPERLY, LOWER PART REPAIRED REPAINTED REFITTED INNER COVER LOOSE	صندوق
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
01.J Sign of back accident		وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسية
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	COMPONENTS REFITTED	الحالة النظرية للمحرك
------------------------------	---------------------	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	FRONT RIGHT SIDE COVER PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		
05.A Gear Box Visual Condition	COMPONENTS REFITTED	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		
06.A Front Tyre	LEFT SIDE 2023,RIGHT 2022,CRACK	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2025,RIGHT 2023 CRACKED	الاطار الخلفي
07 Suspension System		
07.A Other	SUSPENSION PARTS REFITTED	اخرى
08 Interior Condition		
08.A Other	CENTER CONSOLE BOX PANEL MINOR SCRATCHES,REAR CONSOLE BOX COVER NOT CLOSE LOCK NOT WORKING	اخرى
08.B AC Condition	OK	المكيف
08.C Dash Board	PORTION MINOR WORN OUT	لوحة القيادة
08.D Roof Ceiling	PORTION MINOR DIRTY	بطانة السقف
08.E Sun Visor	BOTH SIDE FABRIC PORTION LOOSE	حاجب الشمس
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.G Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae