



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Jan 2022, 18:19:38</b>
Transaction Number	<b>28105836 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>VF37ANFU6EJ517510</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Peugeot</b>
Model	<b>Partner</b>
Model Year	<b>2014</b>
Color	<b>White</b>
Mileage	<b>127424 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
01.B Head Light	LENS MINOR FADED	الاضاءة الرئيسية
01.C Tail Light	REAR LEFT SIDE LIGHT LOOSE	الانارة
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.B AC Condition	OK	المكيف
<b>03 Wipers and Arms</b>		<b>المساحات</b>
03.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
03.B Other	WATER TANK CAP MISSING	اخرى
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Engine Condition	MINOR OIL LEAK,REFITTED	حالة المحرك
04.B Other	ENGINE OIL MEASURE STICK DAMAGED	اخرى
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
05.B Gear Box	SIGN OF MINOR OIL LEAK,REFITTED	الجير
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2018 CRACKED & RIGHT SIDE 2020	الاطار الخلفي
06.C Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Bonnet	GETTING RUSTY&OPENING HANDLE DAMAGED	غطاء المحرك
07.B Roof	WATER LINE RUBBER MISSING	السقف
07.C Paint	BODY MINOR DENT ,SCRATCHES , PORTION PAINT DAMAGED	الصبغ
<b>08 Battery Condition</b>		<b>حالة البطارية</b>
08.A Battery Condition	OK	حالة البطارية
<b>09 Seats Condition</b>		<b>المقاعد</b>
09.A Seat Condition	RIGHT SIDE SEAT MINOR HOLE	حالة المقاعد
09.B Seat Belt	OK	حزام الأمان
<b>10 Steering Condition</b>		<b>المقود</b>
10.A Axel	RIGHT OUTER AXLE BOOT DRY CRACKED	اكسلات
<b>11 Chassis Condition</b>		<b>الشاسي</b>
11.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.