



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **17 May 2023, 17:02:55**
 Transaction Number **71019892 (CC10010)** Queue Number **716336**



Chassis Number **WDDNG71X29A243313**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Mercedes**
 Model **S 500**
 Model Year **2009**
 Color **--**
 Mileage **119878 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Visual Gear Box Condition	NOT CHECKED,	حالة الجير النظري
01.B Propeller Shaft	CENTER BUSHES CRACKED.	ناقل الحركة
01.C Road Test	NOT CHECKED.	فحص علي الطريق
02 Steering Condition		المقود
02.A Axle	BOOT CUT .	اكسلات
02.B Steering Box	OIL LEAK .	جهاز المقود
03 Interior Condition		الحاله الداخليه
03.A AC Condition	NOT CHECKED .	المكيف
03.B Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
04 Body		جسم المركبة
04.A Windshield	FRONT CRACKED .	زجاج
04.B Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES	الصبغ
04.C Vehicle Color	BLACK.	لون المركبة

DEFECT	REMARKS	
04.D Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
04.E Bonnet	LOGO MISSING,GRILL DAMAGE.	غطاء المحرك
04.F Floor	UNDER FLOOR FULLY COVERED,CHECKED ONLY VISIBLE AREA. PORTION DENT.	الارضية
04.G Bumper	MISALIGN PORTION DAMAGE,	دعامية
05 Seats Condition		المقاعد
05.A Seat Condition	BACK COVER LOOSE.	حالة المقاعد
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CRACKED .	أزرع
06.B Shock Absorber	WEAK & BODY LEVEL VERY LOW.	ممتص الصدمات
07 Chassis Condition		الشاسي
07.A Chassis	CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA OK.	الشاسيه
08 Tires and Rims Condition		الاطارات
08.A Rear Tyre	EXPIRED ,CRACKED .	الاطار الخلفي
08.B Front Tyre	EXPIRED ,CRACKED .	الاطار الامامي
09 Lights		الاضاءة
09.A Head Light	LENS FAED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
10 Engine Condition		المحرك
10.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,ENGINE MAJOR PARTS MISSING ,TOP COVER LOOSE ,AIR FILTER ASSEMBLY LOOSE.	حالة المحرك النظري
11 Brake Condition		الفرامل
11.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.