CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3001942
Transaction Date	17 Nov 2026, 14:28:39
Site Name	840 - Emirates Auctions
Transaction Number	11006176 (CC10021) (CC10021)



Vehicle Details

Chassis Number	MR0EW12G6F*******
Specification	GCC Specification
Make	Toyota
Model	Hilux
Model Year	2015
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT LEFT SIDE PORTION DAMAGED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED PORTON RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT,MUDDY	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED . SCRATCHES .	دعامية
01.F Sign of back accident	BACK PANEL , QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS THICK RUST PROOFED,MUDDY,GETTING RUSTY PORTION DENT	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,PARTS REFITTED,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	NOT CHECKED,PARTS REFITTED,PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Lights		**الاضاءة**
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
06.B Tail Light	RIGHT SIDE DAMAGED	الضوء الخلفي
07 Suspension System		**ممتص الصدمات**
07.A Arms	LOWER ARM BUSHES CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Interior Condition		**الحاله الداخليه**
08.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
08.B AC Condition	NOT CHECK	المكيف
08.C Door Panel	WORN OUT	لوحة بطانة الباب
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae