



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 May 2023, 17:01:44
Transaction Number	74965034 (CC10006)	Queue Number	719198



Chassis Number	5FNYF4855FB703113
Engine Number	
Vehicle Class	Car
Manufacturer	Honda
Model	Pilot
Model Year	2015
Color	--
Mileage	190416 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Suspension System</b>		ممتص الصدمات
01.A Ball Joint	BOOT CUT	مفصل كروي
01.B Arms	LOWER ARM BUSHES CUT	ازرع
01.C Shock Absorber	LEAK	ممتص الصدمات
<b>02 Steering Condition</b>		المقود
02.A Tie Rod End	BOOT CUT	مؤخرة الرودات
<b>03 Body</b>		جسم المركبة
03.A Bumper	MISALIGN,PORTION DAMAGE.	دعامية
03.B Vehicle Color	MAROON	لون المركبة
03.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED, DENT,SCRATCHES,PORTION FADED ,PORTION RUSTY	الصبغ
03.D Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
03.E Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED PORTION REPAIRED	مذكور
<b>04 Lights</b>		الاضاءة
04.A Head Light	LENS FADED,	الاضاءة الرئيسية
<b>05 Transmission Condition</b>		الجير

DEFECT	REMARKS	
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	JERKING	حالة الجير النظري
05.C Gear Box Mount	BUSH CRACKED	كرسي الجير
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Smoke	BLACK SMOKE	دخان
06.B Visual Engine Condition	OIL WET	حالة المحرك النظري
06.C Mount	BUSHES CUT	كرسي
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
<b>09 Interior Condition</b>		<b>الحالة الداخليه</b>
09.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.