CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2986558
Transaction Date	13 Nov 2026, 16:27:59
Site Name	840 - Emirates Auctions
Transaction Number	22385954 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1GNWK8EG8D*******
Specification	GCC Specification
Make	Chevrolet
Model	Suburban
Model Year	2013
Color	Yellow
Mileage	78167 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY THICK RUST PROOFED, LOWER PIPE LOOSE	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	PORTION HOLE RUSTY	السقف
01.H Bonnet	REFITTED	غطاء المحرك
01.I Trunk	REFITTED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	RIGHT SIDE CHASSIS SLIGHTLY BEND COMPLETELY THICK RUST PROOFED PROTION RUSTY , DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED & REAR SEAT MISSING MODIFIED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL WET GETTING RUSTY/ MAJOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Other	SUSTENSION GETTING RUSTY REFITTED	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY & CENTER CONSOLE BOX COVER PORTION DAMAGED	اخري
09.B AC Condition	NOT COOLING	المكيف
09.C Dash Board	PORTION DAMAGED	لوحة القياده
09.D Roof Ceiling	PORTION LOOSE	بطانه السقف
09.E Door Panel	PORTION DAMAGED	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae