

Queue Number 2792824

Transaction Date 24 Sep 2026, 13:07:33

Site Name
840 - Emirates AuctionsTransaction Number
53898600 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WD0DA5HB4E*****
Specification	GCC Specification
Make	Mercedes
Model	ML350
Model Year	2014
Color	Black
Mileage	193264 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	RIGHT SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Bonnet	SING REFITTED	غطاء المحرك
01.G Trunk	AUTO NOT WORKING	صندوق
01.H Door Handle & Lock	REAR BOTH SIDE LOCK KNOB COVER MISSING	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH & REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK OPEN REFITTED, SHAKING GETTING RUSTY, DELAY STARTING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACKED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OPEN REFITTED GETTING RUSTY , JERKING	الحالة النظرية للجير
05.B Propeller Shaft	REFITTED, FRONT JOINT INNER RUUBER CUT	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق

06 Tires and Rims Condition

الاطارات

06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط

07 Suspension System

ممتص الصدمات

07.A Arms	LOWER ARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي

08 Steering Condition

المقود

08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
------------------	----------	-----------------

09 Interior Condition

الحالة الداخلية

09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	NOT COOLING , GRILL LOOSE	المكيف
09.C Power Window Switch And Glass	BUTTON PORTION FADED	مفتاح النافذه و الزجاج
09.D Floor Matting	REFITTED	فرش الأرضيه
09.E Audio	SCREEN MODIFIED	صوتيات
09.F Steering Wheel and control buttons	WORN OUT , HARD	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae