



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Nov 2021, 17:52:48
Transaction Number	72321350 (CC10006)	Queue Number	312309



Chassis Number	JMYLRV93W8J732876
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Pajero
Model Year	2008
Color	Silver
Mileage	391272 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALY REPAIRED, REPAINTED EXCEPT ROOF & DENTS, SCRATCHES ON BODY	الصبغ
01.B Fenders	REPAIRED & REPAINTED	مدكار
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Bumper	REPAINTED	دعامية
01.E Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.F Trunk	REPAIRED & REPAINTED	صندوق
01.G Other	FRONT FENDER FRAME, RADITOR SUPPORT REPAIRED	اخرى
01.H Rusty	UNDER BODY PARTS & SUSPENTION GETTING RUSTY	صدأ
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03 Engine Condition		المحرك
03.A Engine Condition	OIL LEAK & REFITTED	حالة المحرك
03.B Other	ENGINE NOT START TO CHECK, ALL SYSTEM NOT CHECK	اخرى
04 Transmission Condition		الجير

DEFECT	REMARKS	
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	NOT CHECK	الجير
05 Lights		الاضاءة
05.A Other	ALL NOT CHECK	اخرى
06 Interior Condition		الحالة الداخليه
06.A AC Condition	NOT CHECK	المكيف
06.B Door Panel	REAR LEFT SIDE STAND HAND DAMAGED	لوحة بطانة الباب
07 Chassis Condition		الشاصي
07.A Chassis	VISABLE AREA OK	الشاسيه
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	NOT CHECK	ازرع المساحات والشفرات
09 Brake Condition		الفرامل
09.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
10 Seats Condition		المقاعد
10.A Seat Condition	SEAT COVER CRACKED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.