



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 May 2023, 11:13:13</b>
Transaction Number	<b>78586301 (CC10008)</b>	Queue Number	<b>726189</b>



Chassis Number	<b>6G1EK5CV7AL446436</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Lumina SS</b>
Model Year	<b>2010</b>
Color	<b>Red</b>
Mileage	<b>306554 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECKED	فحص علي الطريق
01.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظرى
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى
02.B Other	UPPER ENGINE COVER MISSING	اخرى
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rear Tyre	BOTH SIDE 2017 EXPIRED,CRACKED	الاطار الخلفي
03.B Rims Condition	MINOR DENT,SCRATCHES	حالة الجنوط
03.C Front Tyre	BOTH SIDE 2017 EXPIRED,CRACKED,RIGHT SIDE DAMAGED	الاطار الامامي
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Doors	FRONT RIGHT SIDE & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	أبواب
04.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
04.C Bumper	MISALIGN,PORTION DAMAGED	دعامية
04.D Trunk	PORTION REPAIRED,REPAINTED	صندوق

DEFECT	REMARKS	
04.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED	الصبغ
04.F Fenders	REPAINTED,PORTION REPAIRED	مدكار
04.G Floor	PORTION DENT	الارضية
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A AC Condition	NOT CHECK	المكيف
06.B Door Panel	FRONT LEFT SIDE PORTION DAMAGED	لوحة بطانة الباب
06.C Sun Visor	LEFT SIDE MISSING	حاجب الشمس
06.D Other	CENTER CONSOLE BOX COVER DAMAGED	اخرى
06.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.