



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	21 Sep 2021, 12:53:43
Transaction Number	32719595 (CC10006)	Queue Number	312309



Chassis Number	KL1GJ5DU3DB005507
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Malibu
Model Year	2013
Color	Beige
Mileage	131311

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE , REAR BOTH SIDE REPAIRED, REPAINTED & FRONT LEFT SIDE REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	RIGHT SIDE BOTH & REAR LEFT SIDE PORTION REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	REPAINTED	دعامية
01.F Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.G Other	FRONT FENDER FRAME, APRON, WHEEL HOUSING , BUMPER FRAME , RADITOR SUPPORT , BULK HEAD REPAIRED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	FRONT RIGHT SIDE, OUTER SKIRT REPAIRED	الشاسيه
03 Engine Condition		المحرك
03.A Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير

DEFECT	REMARKS	
05.B Gear Box Mount	BUSHES CUT	كرسي الجير
06 Wipers and Arms		المساحات
06.A Other	WORN OUT	اخرى
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
07.B Other	OK	اخرى
08 Brake Condition		الفرامل
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Interior Condition		الاجزاء الداخلية
09.A Other	OK	اخرى
09.B Mirror	OK	المرآيا
09.C AC Condition	A/C NOT COOLING	المكيف
10 Tires and Rims Condition		الاطارات
10.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	KL1GJ5DU3DB005507
Vehicle Make :	CHEVROLET
Vehicle Model :	MALIBU
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Piege
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	131312 Kms.
Origin :	South Korea
Model Year :	2013
Gear Type :	--
Engine No :	121420131
Engine Size :	6000 CC
Axles No :	2
Horse Power :	169
No Of Doors :	4
Cylinders :	4
G. V. W. :	2000 Kgs.
Empty Weight :	1554 Kgs.

Certificate Number :	5-TAS-2021-15080322
Inspection Date :	23-09-2021
Certificate Print Date :	23-09-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	14 min 37 sec
Appointment Ref Number :	--
Start Time :	12:42
End Time :	12:57
Lane :	02
Token No. :	154
Attempt :	1
Prints No :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
3 %	2 %	8 %	0.01 %
Vehicle on Petrol HC Reading			
0 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Arm, mounting, bushes CHANGE FRONT BOTH LOWER ARM BUSHES	Cracked, broken, bend arm	Major
Tire CHANGE FOUR TIRE	Cracked	Major
Gear/Differential CHANGE MOUNTING	Worn out rubber mountings (Major)	Major
Engine CHANGE MOUNTING	Worn out rubber mountings	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	6000	1500	

Inspection Remarks: BULK HEAD REPAIRED , BODY MINOR SCRATCHES AND DENT

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
33695	Cash	15080322	AED 170 Collected on 23/09/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Sittu Paloth Sreesan Paloth

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

