



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>11 Oct 2021, 17:35:47</b>
Transaction Number	<b>51184497 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN8AY2NY2D9057930</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Patrol</b>
Model Year	<b>2013</b>
Color	<b>Silver</b>
Mileage	<b>0 N/A</b>

DEFECT	REMARKS	
<b>01 Wipers and Arms</b>		<b>المساحات</b>
01.A Other	WORN OUT	اخرى
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Other	OK	اخرى
02.B Head Light	OK	الاضاءة الرئيسية
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Paint	TOTALLY REPAINTED , PORTION REPAIRED & DENTS, SCRATCHES ON BODY	الصبغ
03.B Fenders	PORTION REPAIRED & REPAINTED	مدكار
03.C Doors	PORTION REPAIRED & REPAINTED	أبواب
03.D Rusty	UNDER BODY PARTS, SUSPENTION , CHASSIS FRAME GETTING RUSTY	صدأ
03.E Bonnet	SHOCK WEAK	غطاء المحرك
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH 2016 CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2017/2019	الاطار الخلفي
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Other	OK	اخرى
<b>06 Chassis Condition</b>		<b>الشاصي</b>

DEFECT	REMARKS	
06.A Chassis	OK	الشاسيه
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Gear Box	OK	الجير
<b>08 Brake Condition</b>		<b>الفرامل</b>
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>09 Interior Condition</b>		<b>الاجزاء الداخلية</b>
09.A Other	RIGHT SIDE INNER HANDLE DAMAGED & REAR CONSOLE BOX DAMAGED	اخرى
09.B Mirror	OK	المرايا
09.C AC Condition	A/C NOT COOLING & ADJUST SWITCH DAMAED	المكيف
<b>10 Engine Condition</b>		<b>المحرك</b>
10.A Other	OPEN,REFITIED,ONE BOLT MISSING	اخرى
<b>11 Suspension System</b>		<b>ممتص الصدمات</b>
11.A Arms	REAR LOWER ARM BUSHES CRACKED	ازرع
11.B Shock Absorber	FRONT LEFT SIDE LEAK	ممتص الصدمات
<b>12 Steering Condition</b>		<b>المقود</b>
12.A Steering Boot	LEAKING	ربلة المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.