



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 27 Apr 2022, 12:57:51 |
| Transaction Number | 92546615 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | JN1CV6EL1CM471806 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Infiniti |
| Model | G 37 |
| Model Year | 2012 |
| Color | Black |
| Mileage | 61849 Miles |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | USA Imported |

| DEFECT | REMARKS | |
|------------------------------------|---|------------------------|
| 01 Interior Condition | | الحاله الداخليه |
| 01.A Mirror | CENTER MIRROR MISSING | المرابيا |
| 01.B AC Condition | NOT WORKING | المكيف |
| 02 Suspension System | | ممتص الصدمات |
| 02.A Arms | FRONT LOWER ARM BUSH CRACKED | ازرع |
| 03 Tires and Rims Condition | | الاطارات |
| 03.A Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |
| 03.B Front Tyre | BOTH SIDE 2021 | الاطار الامامي |
| 04 Transmission Condition | | الجير |
| 04.A Road Test | NOT CHECK | فحص علي الطريق |
| 04.B Visual Gear Box Condition | MINOR OIL LEAK | حالة الجير النظرى |
| 05 Body | | جسم المركبة |
| 05.A Paint | BODY REPAINTED,PORION REPAIRED,MINOR DENT,SCRATCHES | الصبغ |
| 05.B Fenders | FRONT BOTH SIDE REFITTED | مدكار |

| DEFECT | REMARKS | |
|------------------------------|---|----------------------------|
| 05.C Bonnet | REFITTED | غطاء المحرك |
| 05.D Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 05.E Other | FROTN BUMPER FRAME BULK HEAD FENDER FRAME REPAIRED , RIGHT SIDE APRON ,VIN AREA DENT | اخرى |
| 06 Engine Condition | | المحرك |
| 06.A Visual Engine Condition | MINOR OIL LEAK | حالة المحرك النظرى |
| 07 Chassis Condition | | الشاسي |
| 07.A Chassis | FRONT BOTH SIDE CHASSIS REPAIRED , LEFT SIDE LOWER EDGE MINOR DETACHED | الشاسيه |
| 07.B Chassis Number | CHASSIS NUMBER AREA DENT | رقم القاعدة |
| 08 Lights | | الاضاءة |
| 08.A Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



✓ PASS

| | |
|----------------------------|-------------------|
| Plate Details : | -- |
| Chassis No : | JN1CV6EL1CM471806 |
| Vehicle Make : | INFINITI |
| Vehicle Model : | 37G |
| Vehicle Class : | Light Vehicle |
| Body Type : | Coupe |
| Fuel : | Benzene |
| Color : | Black |
| Drive Direction : | -- |
| Dimensions : (H x W x L) : | -- x -- x -- |
| Current Odometer : | 99539 Kms. |
| Origin : | Japan |
| Model Year : | 2012 |
| Gear Type : | Automatic |
| Engine Size : | 5600 CC |
| Engine No : | NIL |
| Horse Power : | 330 |
| Axles No : | 2 |
| Cylinders : | 6 |
| No Of Doors : | 2 |
| No Of Seats : | 4 |
| G. V. W. : | 2000 Kgs. |
| Empty Weight : | 1450 Kgs. |

Vehicle
Registration



| | |
|---------------------------|---------------------|
| Certificate Number : | 5-TAS-2022-16760279 |
| Inspection Date : | 12-05-2022 |
| Certificate Print Date : | 12-05-2022 |
| Services : | Registration Test |
| Vehicle Testing Partner : | Tasjeel |
| Vehicle Testing Center : | Tasjeel Al Aweer |
| Total Time Taken : | 3 min 38 sec |
| Appointment Ref Number : | -- |
| Start Time : | 17:52 |
| End Time : | 17:55 |
| Lane : | 01 |
| Token No. : | 223 |
| Attempt : | 2 |
| Prints No. : | 1 |

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



7656 KM
Distance per
year



788 L
Fuel consumed
per year



1277 AED
Fuel cost per
year



1.9 ton
Carbon footprint
per year

Inspection Findings

| Discrepancies | Old Value | New Value | Verified |
|--|-----------|-----------|----------|
| Engine Size Discrepancy in Engine Size | 5600 | 3700 | |

Inspection Remarks:

front both side chassis , fender frame , bulk head repaired , ccm passed w/o no - 2022-05-12-4 // vin number area & middle floor dent //

Payment Details

| | | | |
|----------------------------------|-----------------------------------|--------------------------------|--|
| Inspection Performed by 71051 | Payment Method Cash | Transaction Number 16760279 | Service Fees AED 70 Collected on 12/05/2022 |
| Parking Slot No -- | Service Name Registration Test | Attempt 2 | Received by Bajurdeen Abdul Gafoor |

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

