



### Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:	
Transaction Number	: 23521369	Plate Category	:	
Transaction Date	: 11 JAN 2021 07:41:10	Plate Number	:	
Queue Number	: 282276	Import Doc. Ref.	:	58453 EA
Chassis Number	: WBAHN61068DT58453	Manufacturer/Model	:	BMW/740
Engine Number	:	Model Year	:	2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	:	BLACK
Service / Indicator	: DSC AUCTION	Mileage	:	162895

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
05 Body		الهيكل
05.02 - Paint		الصبغ
05.07 - Floor		الارضية
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
06 General Items		الاشياء العامة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
09 Auction		الفحص الكامل
09.06 - Chassis Ok		الشاصي جيد
09.09 - Engine And Gear Box Performance Ok		فحص حالة الماكينة والجير
09.25 - Body Repainted		اثر صبغ في المركبة
		REAR LHS FENDER,LHS BOTH DOORS PORTION REPAINTED

The Test Certificate Shows the test Result at the time of inspection only.  
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط  
تسجيل غير مسؤولة عن العيوب الخفية