





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 25389507	Plate Category	: PRIVATE
Transaction Date	: 06 APR 2021 09:21:00	Plate Number	: 5642 EA
Queue Number	: 318479	Import Doc. Ref.	:
Chassis Number	: JN8BY2NYXK9185642	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2019
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.02 - Tail Lights		الانوار الخلفية
		RIGHT SIDE LOWER CRACK
01.04 - Head Lights		الانوار الامامية
		BOTH SIDE HEAD LIGHT REPLACED
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
		FRONT SUSPENSION RE-FITTED & SUB FRAME REPAIRED
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TIRES 2018
05 Body		الهيكل
05.01 - Rusty		الصدأ
		CHASSIS /SUSPENSION & UNDER BODY COMPONENTS PARTLY RUSTY
05.04 - Fenders		المدكار
		FRONT LEFT SIDE WHEEL HOUSING REPAIRED
05.05 - Bumpers		الدعامية
		BUMPERS REPLACED & REAR BUMPER SUPPORT FRAME REPAIRED
05.08 - Chassis (Frame)		الشاصية
		FRONT BOTH SIDE CHASSIS REPAIRED (HEATED) & REAR RIGHT SIDE END DENT
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
		FRONT WINDSHIELD REPLACED
05.12 - Side Safety Frame		الواقبات الجانبية
		BULKHEAD /RADIATOR SUPPORT & FENDER FRAME REPAIRED
06 General Items		الاشياء العامة
06.08 - Interior Lights		الانوار الداخلية
		DASH BOARD RE-FITTED
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		5645 KM // BONNET & FRONT BOTH SIDE FENDERS REPLACED



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 25389507	Plate Category	: PRIVATE
Transaction Date	: 06 APR 2021 09:21:00	Plate Number	: 5642 EA
Queue Number	: 318479	Import Doc. Ref.	:
Chassis Number	: JN8BY2NYXK9185642	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2019
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.24 - Digital Display Damaged/Warning Lights	CHECK ENGINE LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p>شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية</p>		

Test Certificate

✓ PASS



Registration



RTA

Possession Certificate : 64794456

Chassis No : JN8BY2NYXK9185642

Vehicle Make : NISSAN

Vehicle Model : PATROL

Vehicle Class : Light Vehicle

Body Type : STATION

Fuel : Benzene

Color : White

Drive Direction : --

Dimensions : (H x W x L) --x--x--

Current Odometer : 5644 Kms.

Origin : Japan

Model Year : 2019

Gear Type : --

Engine Size : 2500 CC

Engine No : VQ406958...

Horse Power : 101

Axles No : 2

Cylinders : 4

No Of Doors : 5

No Of Seats : 5

G. V. W. :
2200 Kgs.

Empty Weight : 1650 Kgs.

Certificate Number : 5-MUT-2021-13925275

Inspection Date : 31-03-2021

Certificate Print Date : 31-03-2021

Services : Registration Test

Vehicle Testing Partner : Al Mutakamela Vehicle Testing LLC

Vehicle Testing Center : Al Mutakamela Vehicle Testing Al Qouz

Total Time Taken :
6 min 25 sec

Appointment Ref Number : --

Start Time : 18:16

End Time : 18:22

Lane : 09

Token No. : 565

Attempt : 2

Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



Inspection Findings

Discrepancies

	Old Value	New Value	Verified
Engine Cylinders Incorrect number of cylinders	4	6	
Engine Size Discrepancy in Engine Size	2500	4000	
Seats Incorrect Number of Seats	5	8	

Inspection Remarks:

FRONT RIGHT SIDE CHASSIS LOADING AREA REPAIRED/INNER BEND & LEFT SIDE FRONT CHASSIS END REPAIRED,, HAVE PASS CCM REPORT FROM AL MUTAKAMELA ,, W/O 20210330-01 / TRN 13916011 / DATE 31-03-2021 ...

Payment Details

Inspection Performed by
37987

Payment Method
Cash

Transaction Number
13925275

Service Fees

AED 70 Collected on 31/03/2021

Parking Slot No
--

Service Name
Registration Test

Attempt
2

Received by

Ahmad Samir Qasem Abdulkhaleq

① This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

