CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2940746
Transaction Date	03 Nov 2026, 12:51:09
Site Name	840 - Emirates Auctions
Transaction Number	73303267 (CC10013) (CC10011)



Vehicle Details

Chassis Number	1GYS47KJ0F*******
Specification	GCC Specification
Make	Cadillac
Model	Escalade
Model Year	2015
Color	--
Mileage	183784 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE PORTION SMART REPAINTED,RIGHT SIDE REPAINTED & REAR LEFT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN,MINOR SCRATCHES,REAR PART MISSING	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Vehicle Color	MAROON	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FRAME RUST PROOFED MUDDY DIRTY GETTING RUSTY	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	COVER PORTION CRACK WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK WORN OUT	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Wipers and Arms		**المساحات**
07.A Other	BOTTLE CAP MODIFIED	اخري
08 Lights		**الاضاءة**
08.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		**ممتص الصدمات**
09.A Arms	ARM BUSHES DRY CRACK	ازرع
10 Interior Condition		**الحاله الداخليه**
10.A Other	CENTER CONSOLE BOX COVER LEATHER PORTION LOOSE,SLIDING COVER LOCK NOT WORKING,INTERIOR PARTS GETTING RUSTY	اخري
10.B Mirror	BOTH SIDE COVER MINOR SCRATCHES,INDICATOR LIGHT PORTION DAMAGED	المرايا
10.C AC Condition	OK	المكيف
10.D Audio	LCD TOUCH NOT WORKING	صوتيات
10.E Dash Board	LEATHER PORTION LOOSE	لوحة القياده
10.F Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Engine Start Button	REMOTE PORTION DAMAGED WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae