





Test Certificate

| | | | |
|---------------------|------------------------|--------------------|------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 20229095 | Plate Category | : PRIVATE |
| Transaction Date | : 13 JUL 2020 10:35:04 | Plate Number | : 213416 EA |
| Queue Number | : 195298 | Import Doc. Ref. | : |
| Chassis Number | : JTDBR22E473213416 | Manufacturer/Model | : TOYOTA/COROLLA |
| Engine Number | : | Model Year | : 2007 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|---|------------------------------|
| AUTOMATIC TEST: | | |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| VISUAL TEST: | | |
| 01 Lights | | الانوار |
| 01.04 - Head Lights | LENS FADED | الانوار الامامية |
| 02 Steering And Suspension System | | عجلة القيادة ونظام التوصيلات |
| 02.02 - Steering Mounting, Tight, Crack | STEERING SLIGHT HARD | مثبت عجلة القيادة |
| 02.13 - Stub Axle Assemblies, Boots | AXLE BOOT GREASE LEAK | المحور |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | DOT 1506-4614-1515 | الاطارات الامامية |
| 04.07 - Rims | COVER REMOVED/RUSTY | الرنجات |
| 04.08 - Spare Tires | RIM ONLY | الاطار الاحتياطي |
| 05 Body | | الهيكل |
| 05.02 - Paint | DENT/SCRATCHES | الصدغ |
| 05.03 - Doors | DOOR PORTION RUSTY/REAR LEFT DOOR & DOOR PILLAR REPAIRED/TRUNK DOOR REPLACED | الابواب |
| 05.04 - Fenders | REAR COMPARTMENT & QUARTER PANEL REPAIRED/DOOR PILLAR COVER RUBBER DAMAGED | المدكار |
| 05.05 - Bumpers | FRONT & REAR BUMPER/CRASH BOX/BULKHEAD/FENDER REPAIRED | الدعامية |
| 05.07 - Floor | RIGHT SIDE RUNNING BOARD & LEFT SIDE FLOORING REINFORCEMENT DENT | الارضية |
| 05.08 - Chassis (Frame) | REAR BOTH CHASSIS REPLACED RUSTY/FRONT RIGHT CHASSIS REPAIRED & LEFT SIDE RUSTY | الشاصية |
| 05.10 - All Glasses | REAR RIGHT POWER WINDOW NOT WORKING | الزجاج الجانبي وزجاج الابواب |
| 06 General Items | | الاشياء العامة |
| 06.12 - Seats Condition And Seats Fixing | SEAT & OTHER COMPONENT DIRTY/RIGHT SIDE SUNVISOR MISSING | المقاعد وحالتها وثبيتها |
| 07 Remarks | | ملاحظات |



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 20229095 | Plate Category | : PRIVATE |
| Transaction Date | : 13 JUL 2020 10:35:04 | Plate Number | : 213416 EA |
| Queue Number | : 195298 | Import Doc. Ref. | : |
| Chassis Number | : JTDBR22E473213416 | Manufacturer/Model | : TOYOTA/COROLLA |
| Engine Number | : | Model Year | : 2007 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| | | |
|--|---|-------------------------------|
| 07.04 - Others | 90088 KM CAR WAS USED IN DRIVING SCHOOL | ملاحظات اخرى |
| 09 - Auction | | الفحص الكامل |
| 09.02 - Need Wheel Alignment | SIDE PULLING | بحاجة الى ميزانية العجلات |
| 09.09 - Engine And Gear Box Performance Ok | OK | فحص حالة الماكينة والجير |
| 09.14 - Sign Of Front Accident | | أثر حادث في مقدمة المركبة |
| 09.15 - Sign Of Rear Accident | | أثر حادث في مؤخرة المركبة |
| 09.24 - Digital Display Damaged/Warning Lights | DASHBOARD GUAGE SLIGTH FADED | عطل في لوحة التحكم الالكتروني |
| 09.25 - Body Repainted | BODY PORTION REPAINTED | أثر صيغ في المركبة |
| The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects. | | |