CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899705
Transaction Date	31 Oct 2026, 11:49:06
Site Name	840 - Emirates Auctions
Transaction Number	57758818 (CC10026) (CC10021)



Vehicle Details

Chassis Number	WMWSY3102D*******
Specification	GCC Specification
Make	Mini
Model	Cooper
Model Year	2013
Color	Beige
Mileage	173470 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Bonnet	POTION STICKER	غطاء المحرك
01.F Trunk	PORTION STICKER	صندوق
01.G Vehicle Color	WHITE / BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED , CHECK VISBLE AREA ONLY	الشاسيه
02.B Other	NEED TO REMOVE FENDER INNER & ENGINE COVER FOR PROPER INSPECTION	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED , PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
06.B Indicator & Hazard light	LEFT SIDE INDICATOR HOUSING DAMAGE	الاشارات
06.C Fog light	LENS GETTING FADED	كشاف الضباب
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Odometer reading	CLUSTER DISPLAY PANEL DAMAGE	قراءة عداد المسافات
09.E Door Panel	PORTION LOOSE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	COOLANT MIXED WITH OIL	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae